



5137 HWY 92  
 Acworth GA 30102  
 770-794-0428,  
 Cs@hammockshvac.com

# Invoice39074

<b>DATE</b>	06/16/2025
<b>INVOICE #</b>	39074
<b>TERMS</b>	Due Upon Receipt

## Work Order #744-1

<b>BILL TO</b>
Pure Property Management 17 Aviation Rd SE Marietta, Georgia, 30060-2411  Reymart Blaza 770-427-5711 rblaza@rentpure.com

<b>SERVICE LOCATION</b>
Pure Property Management  659 Auburn Ave NE Atlanta, Georgia, 30312-1903 770-427-5711 rblaza@rentpure.com

<b>JOB#</b>	<b>DATE</b>	<b>TECH</b>	<b>PO</b>	<b>COMPLETION NOTES</b>
106888507 6	06/16/2025	Jamal		TENANT: Jordan Mitchell 404-838-8373 **SERVICE CALL** Water actively leaking from unit LIMIT PRICE IS \$500 <b>Completion Notes:</b> Upon arrival I found the system cooling but the primary drain was clogged. After clearing the drain with nitrogen and cleaning the p-trap, I was able to get the system draining properly. I added ¾ pvc unions for easy access when cleaning the drain in the future.

	<b>Description</b>	<b>Qty</b>	<b>Rate</b>	<b>Total</b>
	<b>SERVICE CALL</b> DIAGNOSTIC OF EQUIPMENT.	1.00	\$85.00	\$85.00
	<b>R-DRAIN CLEAR</b> R-DRAIN CLEAR: INCLUDES MATERIALS AND NITROGEN FLUSH OF DRAIN LINE. 30 DAY WARRANTY.	1.00	\$83.00	\$83.00

<b>R-LABOR</b>	1.00	\$165.00	\$165.00
Cleaning the p-trap and modifying the primary drain for easy access moving forward.			

**SUB-TOTAL:**  
\$333.00

**TIME & LABOR:**  
\$0.00

**EXPENSES:**  
\$0.00

**PMTS/DEPS:**  
\$0.00

**TOTAL DUE:**  
\$333.00

<b>CUSTOMER MESSAGE</b>

<b>Invoice Total:</b>	<b>\$333.00</b>
<b>Deposits (-):</b>	<b>\$0.00</b>
<b>Payments (-):</b>	<b>\$0.00</b>
<b>Total Due:</b>	<b>\$333.00</b>